

Post-Hurricane Sandy Status Report for Region 2 Superfund Remedial Sites
Located in Emergency Declaration Counties

Full, Official Site Name: **Cornell-Dubilier Electronics Superfund Site**

Site Address or Location, including County: **333 Hamilton Blvd, Middlesex County, South Plainfield, New Jersey, 07080**

Lat/Long for Site (if you can get this information):

Date of Inspection: **November 8, 2012**

Name of Inspector: **Patrick Nejand**

Affiliation of Inspector (EPA/Contractor/PRP/etc.): **U.S. Army Corps of Engineers**

Best phone number to reach inspector: **908 769-1601**

Do conditions at the site pose an immediate threat to human health or the environment?

☐ Yes ☒ No

If Yes, please provide a brief description of the conditions and the necessary response actions:

Briefly describe any equipment damage, operational problems, etc.:

On November 8, 2012 the U.S. Army Corps of Engineers performed further inspections of the Cornell site and surrounding areas, and identified debris in on-site drainage structures that could reduce the flow of water in the bound brook and some damage fencing. USEPA has directed the contractor (USACE and Severson Environmental) to clean out the drains and fix the fencing. The USEPA will be notified once the work has been completed.